

FIG. 1 PRIOR ART






FIG.5



9



F | G. 4

Condition	
Sink mark Flash Warpage Silver Short Weld lines	
Quality	—23
Better Worse	
Setting	232

FIG.6





FIG.7






FIG. 10